CONTRIBUTING RESOURCE MARYLAND HISTORICAL TRUST INTERNAL NR-ELIGIBILITY REVIEW FORM

Property Name: <u>511 East 43rd Street</u> , <u>Baltimore City</u> Survey Number: <u>BC B-5043</u>			
Property Address: <u>511 East 43rd Street</u> , <u>Baltimore City</u>			
Project: Rehabilitation 511 E. 43rd St. Agency: CDA (State)			
Site visit by MHT Staff: no _X_ yes Name _E. Hannold DateMarch 17, 19			
District Name:Old York Road/E. 43rd area Survey Number:n/a			
ListedX_ Eligible <u>district with unkown boundaries identified 3/17/93</u> Comme			
Criteria: $XA = B = XC = D$ Considerations: $A = B = C = D = E = F = G = NC$			
The resource X contributes/ does not contribute to the historic significance of the historic district in: X Location X Design X Setting X Materials			
Workmanship Feeling Association			
Justification for decision: (Use continuation sheet if necessary and attach map)			
The building at 511 East 43rd Street is eligible for the National Register of Historic Places as a contributing resource in the surrounding district. The largely residential area is located just off the heavily commercial York Road corridor between Waverly and Govans is characterized by an irregular street plan and a wide variety of middle and working class housing types. The area is representative of Baltimore's early suburban development. Located outside the city until 1918, the suburban character of the area is reflected in the prevalance of single-family houses set on small lots. The area apparently developed slowly, from perhaps the 1870s through the 1940s, as shown in its houses ranging from frame gable front houses to blocky brick rowhouses of the 1940s. East 43rd Street is characterized by larger and more architecturally distinguished buildings than the surrounding streets and includes several large shingle style houses, a stone chuurch and manse, and the building at 511 East 43rd Street.			
Documentation on the property is presented in: Project file			
Preparedy:			
Elizabeth Hannold March 23, 1993 Reviewer, Office of Preservation Services Date			
program congurrence: 🗶 yes no not applicable			
K. Undrum 3.23.93			
Revièwer, NR program Date			

grug


Survey No. _BC-_ B-5043

MARYLAND COMPREHENSIVE HISTORIC PRESERVATION PLAN DATA - HISTORIC CONTEXT


I.	Geographic Region:		
_	Eastern Shore Western Shore	(all Eastern Shore counties, and Cecil) (Anne Arundel, Calvert, Charles, Prince Coorgo's and St. Many's)	
<u>X</u>	Piedmont	Prince George's and St. Mary's) (Baltimore City, Baltimore, Carroll, Englopick, Hanford, Howard, Montgomory)	
	Western Maryland	Frederick, Harford, Howard, Montgomery) (Allegany, Garrett and Washington)	
II.	Chronological/Developmental Periods:		
	Paleo-Indian Early Archaic Middle Archaic Late Archaic Early Woodland Middle Woodland Late Woodland/Archaic Contact and Settlement Rural Agrarian Intensification Agricultural-Industrial Transi Industrial/Urban Dominance Modern Period Unknown Period (prehisto	A.D. 1815-1870 A.D. 1870-1930 A.D. 1930-Present	
III.	Prehistoric Period Themes:	IV. Historic Period Themes:	
	Subsistence Settlement Political Demographic Religion Technology Environmental Adaption	Agriculture X Architecture, Landscape Architecture, and Community Planning Economic (Commercial and Industrial) Government/Law Military Religion Social/Educational/Cultural Transportation	
V. Resource Type:			
	Category: Building Historic Environment: Suburban Historic Function(s) and Use(s): Residential (multi-family)		
Known Design Source: Unknown			
distribution:			


The building at 511 East 43rd Street was appears to have been designed as an apartment building and some attempt was made to relate the design to the surrounding single-family residential character of the neighborhood. Now stuccoed, the building was originally clad in clapboards, like several neighboring houses. The height was kept to three stories and mass broken up by projecting bays, an addition-like, rear section and a complex roof line. In addition, the building was sited on a large lot.

Although heavily damaged by fire and water, the building still contributes to the district in terms of location, design and setting.



B-5043 511 E. 43rd Street Block 5202 Lot 013 Baltimore City Baltimore East Quad.





B-5043, 511 East 43 nd St, Bret, City



Biso East 43nd St, Back, Cty

TYPICAL WALL SECTION



377 East 43nd St, Back, City

ENTRANCE HALL, MAIN STAIR



511 East 43nl St., Bactimese City

WEST SIDE

571 East 43nd St. Balt. City B-2043

FRONT ENTRANCE



571 East 43nd St., Back, City